

Single Phase Input: 208 - 245 Volts

3 Phase Rated Output: 208 - 245 Volts

Minimum Single Phase Circuit: 20 Amps

Best Performance Single Motor Start: 3HP

Recommended 3 Phase Sizing: 11 Amps

Voltage Balance: +/-2-5% (Based on input)

**Professional. Rugged. Affordable.** Pro-Line offers more than a traditional a phase converter. Built complete and loaded with features.




## **Control Panel Features**

- Integrated Motor Starter with Start/Stop Push Button Switch
- Digitally Controlled & Protected Start Circuit
- Complete Phase Power Failure Protection
- CNC Voltage Balancing
- Power "ON" Indicator Light
- Easy Power Distribution Block Connections
- 10 Year Parts / Lifetime Labor Warranty
- Made In the USA

## **Idler Generator Features**

- Custom Design Rotary Phase Converter Generators
- Low Impedance/High Efficiency Design
- Custom Copper Windings and Rotor
- Made by ABB / Baldor Electric USA
- Available in ODP and TEFC
- Soft Start Idler Generator
- Shielded Windings
- Made In the USA







## Specifications

Model	
Brand	NAPCES
Line	Pro-Line
Model #	PL-7
General Specifications	
Horse Power (HP)	7.5
Kilo-watt (kW)	5.6
Frequency (Hz)	60
Generator Type	ODP
Enclosure Type	NEMA 1 (Indoor)
Generator Frame	213
Single Phase Electrical Specifications	
Voltage Input	208-245
Minimum Fuse Size	20
Minimum Circuit Breaker Size	20
Maximum Fuse Size	40
Maximum Circuit Breaker Size	40
Minimum Wire Input	8 AWG
Idle Amperage	4.24
Three Phase Electrical Specifications	
Voltage Output	208-245 based on input voltage
Output Amperage	20
Voltage Balance	2 - 5%
Minimum Wire to Generator	10 AWG
Minimum Wire to Load	10 AWG
Dimensions & Weights	
Enclosure (H X W X D)	17" X 12" X 8"
Idler (Approx.) Length X Diameter	13" X 8"
Approx. Total Shipping Weight	110 lbs.

The PL-7 Pro-Line Phase Converter is best sized for:	
Easy / Light Motor Loads - up to 5HP	
Examples of Easy Loads: Table Saw, Milling Machine ,Drill Press	
Medium Motor Loads - up to 5HP	
Examples of Medium Loads: Belt Sander, Grinder, Mixer	
Hard Motor Loads - up to 3HP	
Examples of Hard Loads: Gearhead Lathe, Dust Collector , Fan	
Very Hard Motor Load - up to 2HP	
Examples of Very Hard Motor Loads: Air Compressor, Sub. Pump	
CNC, Resistive and Inductive Loads - up to 11 Amps @240 volts	

Sizing Notes PL-7

**For light/easy motor loads:** Size rotary phase converter up one size above motor size

For medium motor loads: Size rotary phase converter 1.5 times larger then motor size  $\,$ 

For heavy/hard motor loads: Size rotary phase converter double the size of motor load

**For very hard motor loads:** Size rotary phase converter 2.5 times larger then the motor load

**For CNC, resistive and inductive loads:** Size rotary phase converter double the size of load





**Wired and Wireless Remote Switches** 



**Twist-Lock Outlets and Plugs** 



**Floor Mounting Kits** 



